

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:					
OGM	Joe Helfrich Environmental Scientist III				
Company	Dan Guy				

# **Inspection Report**

Permit Number:	C0070016		
Inspection Type:	PARTIAL		
Inspection Date:	Wednesday, April 21, 2004		
Start Date/Time:	04/21/2004 9:30:00 AM		
End Date/Time:	04/21/2004 2:00:00 PM		
Last Inspection:	Thursday, March 18, 2004		

Inspector: Joe Helfrich, Environmental Scientist III

Weather: cold snowing

InspectionID Report Number: 248

Accepted by: dhaddock 04/26/2004

Permitee: MOUNTAIN COAL CO
Operator: MOUNTAIN COAL CO

Site: GORDON CREEK 2, 7 & 8 MINES

Address: HC 35 BOX 380, HELPER UT 84526

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages	Mineral Ownership	Types of Operations	
180.00 Total Permitted	✓ Federal	<b>✓</b> Underground	
34.88 Total Disturbed	☐ State	Surface	
Phase I	☐ County	☐ Loadout	
Phase II	<b>✓</b> Fee	Processing	
Phase III	☐ Other	Reprocessing	

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

The purpose of this site visit was to conduct a partial inspection of the reclaimed Gordon Creek 2,7 & 8 site. The permit status is described under standard # 1.

Joe Helfrich, Environmental Scientist III

Inspector ID Number: 1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining



Permit Number: C0070016 Inspection Type: PARTIAL

Inspection Date: Wednesday, April 21, 2004

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	$\checkmark$		<b>✓</b>	
2.	Signs and Markers	<b>✓</b>		<b>✓</b>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		<b>✓</b>	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.	b Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070016
Inspection Type: PARTIAL

Inspection Date: Wednesday, April 21, 2004 Page 3 of 3

## 1. Permits, Change, Transfer, Renewal, Sale

The permit for this reclaimed site was renewed effective August 28, 1999. The five year permit renewal application is due on April 28, 2004. The requirements for renewal were discussed during the inspection. There is one amendment pending, #AM02A, (Rock Gabion removal) submitted on March 13, 2002. The TA contained one deficiency requiring the applicant to demonstrate that no additional contributions of suspended solids were occurring in the receiving stream channel and to prevent material damage outside the permit area. No samples have been taken to date. On May 22, 2003, the Division conducted a Phase One bond release inspection for the reclaimed area, and a Phase Three bond release inspection for the Sweets Pond area. Other agencies represented were BLM, Steve Faulk, and OSM, Mitch Rollings. Mountain Coal representatives included Dan Guy, Vicky Miller, and Chris Hansen. Bond release for both areas was approved October 6, 2003.

## 2. Signs and Markers

The sign with the required information was posted at the entrance to the reclaimed area.

#### 4.b Hydrologic Balance: Sediment Ponds and Impoundments

It was snowing and blowing at the site. However, the ponds appeared to be in stable condition.